



ALLIANCE GEOSYNTHETICS

Case Study 73

Project Name:

Highway 50

Location:

Omaha, NE

Date:

Summer 2016

Product:

AllianceGeo RG2010 (20,000 SY)

Owner/Developer:

Nebraska Department of Roads

Civil Engineer:

Nebraska Department of Roads

Contractor:

Henningsen Construction



Application / Problem Description:

Reflective crack control on busy highway.

Solution:

Following the addition of a shoulder lane, a longitudinal crack formed between the existing road and the shoulder. AllianceGeo's RoadGrid product was placed over this crack to help mitigate reflective cracking in the future.

For more information on Alliance Geosynthetics products, call 1.877.454.8096

Alliance Geosynthetics 444 Lane Avenue Drain, OR 97435 f: 541.391.4805 www.alliancegeo.com